Annexure-D

BUILDING SAFETY CERTIFICATE

No. **32** Dated: **14/08/2026**

It is certified that the existing building – **ST. JOSEPH'S SCHOOL**– (name of the building or premises)

at **CIVIL LINES, DISTRICT PRATAPGARH, U.P. 230001** (address)is having block(s) /Floor(s)as per details below:

Detail of Block(s)in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	**GROUND + 02**	N.A.	N.A.	N.A.	N.A.	N.A.

The building is owned/occupied by **ST. JOSEPH'S SCHOOL - CIVIL LINES, DISTRICT PRATAPGARH, U.P. 230001** (name of the Institution) have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **RC Maurya- Rural Engineering Department Division – Pratapgarh, Uttar Pradesh** (Name of Department/Govt.) on **14/08/2026** (date of inspection) in the presence of **Fr. Robert Sunil Noronha.**

The **ST. JOSEPH'S SCHOOL, CIVIL LINES, DISTRICTPRATAPGARH, U.P. 230001** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **14/08/2026 for** a period of **13/08/2036** (**10 years**) in accordance with rule and subject to compliance of the specific conditions as appended. -1. N.A.

Issued on **14/08/2026** at **Pratapgarh** by **Assistant Engineer-- Rural Engineering Department Division – Pratapgarh, Uttar Pradesh**

Signature with Seal: _____

Name: (R.C. Maurya)

Designation: Assistant Engineer
Rural Engineering Department

Name & Address of Department/Office: Division-Pratapgarh

Scanned with OKEN Scanner